

QUICK TURN 100MS (300U)

Universal	Universal type	12 "
Capacity	Max. swing	Φ22 "
	Max. machining diameter	Φ11 "
	Max. machining length	16 "
	Bar work capacity	Φ2 "
Spindle	Chuck size	6 "
	Max. spindle speed	6000 rpm
	Spindle motor (30 min. rating)	11 kW (15 HP)
Second spindle	Chuck size	5 "
	Max. spindle speed	6000 rpm
Turret	Tool storage capacity	12
Travel	X-axis	7 "
	Z- axis	20 "
*1 Varies depending on the CNC system.		